

# Oil Field Environmental Incident Summary

**Incident:** 20140103133120 **Date/Time of Notice:** 01/03/2014 13:20

**Responsible Party:** XTO Energy

**Well Operator:** XTO ENERGY INC.

**Well Name:** STATE 11-16H

**Field Name:** CHARLSON

**Well File #:** 17221

**Date Incident:** 1/3/2014 **Time Incident:** 09:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 16

**Qtr:**

**Location Description:**

**Submitted By:** Shawn Dahl

**Received By:**

**Contact Person:** Shawn Dahl  
P.O Box 1589  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	80	barrels	0	barrels	5	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/19/2015

**Clean Up Concluded:** 1/21/2014

**Risk Evaluation:**

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

on location in a lined metal berm. The suction valve was closed. Vac truck will collect free liquids.

**Wastes Disposal Location:** liquids will be put back in production tank. removal of impacted soil will take place when weather permits. and hauled to an approved disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 1/3/2014      **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill was confined to a steel lined dike. NDIC retains oversight.